Appendix A - Site Plan and Proposed Land Application Area



GEOplan

Geoscience + Planning

Land application Area Summary

Indicative General Site Design Recommendations Summary (CoP Dev Flow Rate and CoP BOD)

Treatment Standard	Septic Tank Capacity (Litres)	Land Application Method	Construction Requirements (Reference AS/NZS 1547/2012 Construction Diagram)	Calculated Length (m)*	Indicative LAA Area (m²)*
Primary or Secondary Treatment (AWTS or Sand Filter)	3000L (3BR) 4000L (4BR) 4500L (5BR)	Trench (Secondary Treatment)	L	120m (3BR) 160m (4BR) 193m (5BR)	264 m² 351m² 434m²
		ETA/ETS	L6 & L	205m 257m 309m	510 m² 660 m² 750 m²
		Subsurface Irrigation*	M1	320 m² (3 Bedroom) 400 m² (4 Bedroom) 475 m² (5 Bedroom)	

*Using a water balance as shown at Appendix C

Where

Trench length does not exceed 30m

Trench/bed Width - 0.9m

Trench/Bed Spacing - 2m

Per metre Land Application Area Buffer 0.5m

Notes:
For setback distances refer to EPA Publication 891.4 (*Guidelines for Environmental Management Code of Practice Onsite Wastewater Management).* All *CoP* setbacks can be achieved. Land application shown not to scale.

Disclaimer
Due regard has been made to undertake all aspects of this study in accordance with the requirements of best practice and relevant standards. LAA calculations have been made with due regards to AS/NZS 1547:2012 and whilst the findings ontained in this report represent a reasonable interpretation of site conditions, it does not indicate that these findings represent the actual state of the site at all points. The complex interactions between soil, climate, topography and wastewater mean that there is no one correct answer and the nominated results should be viewed in this context. The paucity of specific evaporation data is a limiting factor with regard to LAA calculations.

Appendix B – Soil Profiles

Profile 1

Profile 2

Profile 3

GEOplan

Geoscience + Planning

Client: Martin Job: 1708 Excavation Number: 1 Logged by: SH

Address: Cemetery Rd Bathurst Surface level: R L

Date of inspection: 8 July 2017

Slope: 10 % Land form element: Wax - Div Surface conditions: Moist Indicative drainage:

Surface stones: Limited Ground cover: pasture Watertable depth: > 1 m

Land surface notes: Parent material: Gneiss

Layer	Lower depth (mm)	Horizon	Moisture conditions (see Note 2)	Colour (moist)	Field texture	Coarse fragments % volume	Structure (see Note 3)	Modified Emersion	Sample taken (Y/N)	Consistency (see Note 4)	Soil category	Other assessment
1	A1 – 100mm		Moist	DK BR	FSL	<5%	MOD		N	WK		
2	A2 – 200mm		Moist	YL-BR	CL-LM	1	MOD		N	WK		
3	B1 – 600mm		Dry	BR-GR	SANDY CL	1	MOD		Y	RIGID	5C	
4	B2 – 1000mm		Dry	YL-GR	SANDY CL	1	WK		Y	WK	5C	
5												

NOTES:
1 Use another form if >5 layers on major horizons.
2 Dry, moist, very moist, saturated.
3 Apedal (no peds) Either single grain or massive
Pedal (observable peds) Weak, moderate or strong.
4 Strength – loose, very weak, weak, firm, very firm, strong, very strong, rigid.
Stickiness (when wet) – non, slightly, moderately, very

Notes/comments/observations:

Organisational details/Logo:

Overall soil category assigned: 5C Maximum depth of system: 7000mm

Soil appears favourable for (list system types): Checked by:

FIGURE B1 SITE-AND-SOIL EVALUATION FORM: EXCAVATION LOG – EXAMPLE

Client: Martin Job: 1708 Excavation Number: 2 Logged by: GH

Address: Cemetery Rd Bethanga Surface level: R L

Date of inspection: 4 July 2017

Slope: 10 % Land form element: Wav-Dil Surface conditions: Moist Indicative drainage:

Surface stones: limited Ground cover: Pasture Watertable depth: 7M

Land surface notes: Parent material:

Layer	Lower depth (mm)	Horizon	Moisture conditions (see Note 2)	Colour (moist)	Field texture	Coarse fragments % volume	Structure (see Note 3)	Modified Emersion	Sample taken (Y/N)	Consistency (see Note 4)	Soil category	Other assessment
1	100	A1	MOIST	GR-BR	FSL	<5%	MOD		N	WEAK		
2	200	A2	MOIST	GRL-BR	CL-LM	"	MOD		N	WEAK		
3	400	B1	Dry	BR-GR	LT-CL	"	MOD		N	RIGID		
4	1000	B2	Dry	YL-BR	SANDY CL	"	WK		N	WEAK	5C	
5												

NOTES:
1 Use another form if >5 layers on major horizons.
2 Dry, moist, very moist, saturated.
3 Apedal (no peds) Either single grain or massive.
Pedal (observable peds) Weak, moderate or strong.
4 Strength – loose, very weak, weak, firm, very firm, strong, very strong, rigid.
Stickiness (when wet) – non, slightly, moderately, very.

Notes/comments/observations:

Organisational details/Logo:

Overall soil category assigned: 5C Maximum depth of system: >1000mm

Soil appears favourable for (list system types): Checked by:

FIGURE B1 SITE-AND-SOIL EVALUATION FORM: EXCAVATION LOG – EXAMPLE

Client: Martin Job: 1708 Excavation Number: 3 Logged by: SH

Address: Cemetery Rd Bethanga Surface level: R L

Date of inspection: 4 July 2012

Slope: 10 % Land form element: Wax-Div. Surface conditions: Moist Indicative drainage:

Surface stones: Limited Ground cover: Pasture Watertable depth: >1M

Land surface notes: Parent material:

Layer	Lower depth (mm)	Horizon	Moisture conditions (see Note 2)	Colour (moist)	Field texture	Coarse fragments % volume	Structure (see Note 3)	Modified Emersion	Sample taken (Y/N)	Consistency (see Note 4)	Soil category	Other assessment
1	100	A1	MOIST	GR-BR	FSL	<5%	MOD		N	MOD		
2	300	A2	MOIST	GR-BR	CL-LM	"	MOD		N	MOD		
3	600	B1	DRY	BR-GR	L-CL	"	MOD		N	RIGID		
4	1000	B2	DRY	YL-GR	SANDY CLAY	"	WEAK		N	WEAK	5C	
5												

NOTES:
1 Use another form if >5 layers on major horizons
2 Dry, moist, very moist, saturated
3 Apedal (no peds) Either single grain or massive
Pedal (observable peds) Weak, moderate or strong.
4 Strength – loose, very weak, weak, firm, very firm, strong, very strong, rigid
Stickiness (when wet) – non, slightly, moderately, very.

Notes/comments/observations:

Organisational details/Logo:

Overall soil category assigned: 5C Maximum depth of system: >1000mm

Soil appears favourable for (list system types): Checked by:

FIGURE B1 SITE-AND-SOIL EVALUATION FORM: EXCAVATION LOG – EXAMPLE

Appendix C – Water Nutrient Balances

Spreadsheet Prepared by Paul Williams & Associates Pty Ltd for use by GeoPlan Consulting

WATER/NITROGEN BALANCE (20/30 irrigation): 3 Bedroom - with no wet month storage.

Rainfall Station: Albury Aiport AWS Evaporation: BOM

Location: Bethanga

Date: August, 2017

Client: Martin

ITEM	UNIT	#	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	YEAR
Days in month:		D	31	28	31	30	31	30	31	31	30	31	30	31	365
Evaporation (Mean)	mm	A	250	200	175	90	50	30	30	50	80	125	200	200	1480
Rainfall (9th Decile wet year adjusted)	mm	B1	73	81	67	94	105	105	99	103	111	104	104	72	1118
Effective rainfall	mm	B2	66	73	60	85	95	94	89	93	100	93	93	65	1005
Peak seepage Loss[1]	mm	B3	155	140	155	150	155	150	155	155	150	155	150	155	1825
Evapotranspiration(IXA)	mm	C1	100	80	70	36	20	12	12	20	32	50	80	80	592
Waste Loading(C1+B3-B2)	mm	C2	189	147	165	101	80	68	78	82	82	112	137	170	1412
Net evaporation from lagoons (10(0.8A-B1xlagoon area(ha)))	L	NL	0	0	0	0	0	0	0	0	0	0	0	0	0
Volume of Wastewater	L	E	22320	20160	22320	21600	22320	21600	22320	22320	21600	22320	21600	22320	262800
Total Irrigation Water(E-NL)/G	mm	F	70	63	70	68	70	68	70	70	68	70	68	70	821
Irrigation Area(E/C2)annual	m^2	G													320
Surcharge	mm	H	-119	-84	-95	-34	-10	0	-8	-13	-15	-42	-69	-100	0
Actual seepage loss	mm	J	36	56	60	116	145	150	147	142	135	113	81	55	1234
Direct Crop Coefficient:		I	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade:

Rainfall Retained:	90	%	K
Lagoon Area:	0	ha	L
Wastewater(Irrigation):	720	L	M
Seepage Loss (Peak):	5	mm	N
Irrig'n Area(No storage):	320	m^2	P2
Application Rate:	2.3	mm	Q
Nitrogen in Effluent:	30	mg/L	R
Denitrification Rate:	20	%	S
Plant Uptake:	220	kg/ha/yr	T
Mean daily seepage loss:	3.4	mm	U
Annual N load:	6.31	kg/yr	V
Area for N uptake:	287	m^2	W
Application Rate:	2.5	mm	X

1. Seepage loss (peak) equals deep seepage plus lateral flow:8mm (<10% ksat)

CROP FACTOR

M	0.7	0.7	0.7	0.6	0.5	0.45	0.4	0.45	0.55	0.65	0.7	0.7	Pasture:
N	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade:
P2	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	Fescue:
Q	0.8	0.8	0.7	0.7	0.6	0.6	0.6	0.6	0.7	0.8	0.8	0.8	MAR:

NITROGEN UPTAKE:

Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH
Ryegrass	200	5.6-8.5	Bent grass	170	5.6-6.9	Grapes	200	6.1-7.9
Eucalyptus	90	5.6-6.9	Couch grass	280	6.1-6.9	Lemons	90	6.1-6.9
Lucerne	220	6.1-7.9	Clover	180	6.1-6.9	C cunn'a	220	6.1-7.9
Tall fescue	150-320	6.1-6.9	Buffalo (soft)	150-320	5.5-7.5	P radiata	150	5.6-6.9
Rye/clover	220		Sorghum	90	5.6-6.9	Poplars	115	5.6-8.5

Spreadsheet Prepared by Paul Williams & Associates Pty Ltd for use by GeoPlan Consulting

WATER/NITROGEN BALANCE (20/30 irrigation): 4 Bedroom - with no wet month storage.

Rainfall Station: Albury Aiport AWS Evaporation: BOM

Location: Bethanga
Date: August, 2017
Client: Martin

ITEM	UNIT	#	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	YEAR
Days in month:		D	31	28	31	30	31	30	31	31	30	31	30	31	365
Evaporation (Mean)	mm	A	250	200	175	90	50	30	30	50	80	125	200	200	1480
Rainfall (9th Decile wet year adjusted)	mm	B1	73	81	67	94	105	105	99	103	111	104	104	72	1118
Effective rainfall	mm	B2	66	73	60	85	95	94	89	93	100	93	93	65	1005
Peak seepage Loss[1]	mm	B3	155	140	155	150	155	150	155	155	150	155	150	155	1825
Evapotranspiration(IXA)	mm	C1	100	80	70	36	20	12	12	20	32	50	80	80	592
Waste Loading(C1+B3-B2)	mm	C2	189	147	165	101	80	68	78	82	82	112	137	170	1412
Net evaporation from lagoons (10(0.8A-B1xlagoon area(ha)))	L	NL	0	0	0	0	0	0	0	0	0	0	0	0	0
Volume of Wastewater	L	E	27900	25200	27900	27000	27900	27000	27900	27900	27000	27900	27000	27900	328500
Total Irrigation Water(E-NL)/G	mm	F	70	63	70	68	70	68	70	70	68	70	68	70	821
Irrigation Area(E/C2)annual.	m^2	G													400
Surcharge	mm	H	-119	-84	-95	-34	-10	0	-8	-13	-15	-42	-69	-100	0
Actual seepage loss	mm	J	36	56	60	116	145	150	147	142	135	113	81	55	1234
Direct Crop Coefficient:		I	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade

Rainfall Retained:	90	%	K
Lagoon Area:	0	ha	L
Wastewater(Irrigation):	900	L	M
Seepage Loss (Peak):	5	mm	N
Irrig'n Area(No storage):	400	m^2	P2
Application Rate:	2.3	mm	Q
Nitrogen in Effluent:	30	mg/L	R
Denitrification Rate:	20	%	S
Plant Uptake:	220	kg/ha/yr	T
Mean daily seepage loss:	3.4	mm	U
Annual N load:	7.88	kg/yr	V
Area for N uptake:	358	m^2	W
Application Rate:	2.5	mm	X

1. Seepage loss (peak) equals deep seepage plus lateral flow:8mm (<10% ksat)

CROP FACTOR	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	
	0.7	0.7	0.7	0.6	0.5	0.45	0.4	0.45	0.55	0.65	0.7	0.7	Pasture
	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade
	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	Fescue
	0.8	0.8	0.7	0.7	0.6	0.6	0.6	0.6	0.7	0.8	0.8	0.8	MAV

NITROGEN UPTAKE:

Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH
Ryegrass	200	5.6-8.5	Bent grass	170	5.6-6.9	Grapes	200	6.1-7.9
Eucalyptus	90	5.6-6.9	Couch grass	280	6.1-6.9	Lemons	90	6.1-6.9
Luceme	220	6.1-7.9	Clover	180	6.1-6.9	C cunn'a	220	6.1-7.9
Tall fescue	150-320	6.1-6.9	Buffalo (soft)	150-320	5.5-7.5	P radiata	150	5.6-6.9
Rye/clover	220		Sorghum	90	5.6-6.9	Poplars	115	5.6-8.5

Spreadsheet Prepared by Paul Williams & Associates Pty Ltd for use by GeoPlan Consulting

WATER/NITROGEN BALANCE (20/30 irrigation): 5 Bedroom - with no wet month storage.

Rainfall Station: Albury Aiport AWS Evaporation: BOM

Location: Bethanga

Date: August, 2017

Client: Martin

ITEM	UNIT	#	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	OCT	NOV	DEC	YEAR
Days in month:		D	31	28	31	30	31	30	31	31	30	31	30	31	365
Evaporation (Mean)	mm	A	250	200	175	90	50	30	30	50	80	125	200	200	1480
Rainfall (9th Decile wet year adjusted)	mm	B1	73	81	67	94	105	105	99	103	111	104	104	72	1118
Effective rainfall	mm	B2	66	73	60	85	95	94	89	93	100	93	93	65	1005
Peak seepage Loss[1]	mm	B3	155	140	155	150	155	150	155	155	150	155	150	155	1825
Evapotranspiration(IXA)	mm	C1	100	80	70	36	20	12	12	20	32	50	80	80	592
Waste Loading(C1+B3-B2)	mm	C2	189	147	165	101	80	68	78	82	82	112	137	170	1412
Net evaporation from lagoons (10(0.8A-B1xlagoon area(ha)))	L	NL	0	0	0	0	0	0	0	0	0	0	0	0	0
Volume of Wastewater	L	E	33480	30240	33480	32400	33480	32400	33480	33480	32400	33480	32400	33480	394200
Total Irrigation Water(E-NL)/G	mm	F	70	64	70	68	70	68	70	70	68	70	68	70	830
Irrigation Area(E/C2)annual.	m^2	G													475
Surcharge	mm	H	-119	-83	-95	-33	-10	0	-7	-12	-14	-41	-69	-100	0
Actual seepage loss	mm	J	36	57	60	117	145	150	148	143	136	114	81	55	1243
Direct Crop Coefficient:		I	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade

Rainfall Retained:	90	%	K
Lagoon Area:	0	ha	L
Wastewater(Irrigation):	1080	L	M
Seepage Loss (Peak):	5	mm	N
Irrig'n Area(No storage):	475	m^2	P2
Application Rate:	2.3	mm	Q
Nitrogen in Effluent:	30	mg/L	R
Denitrification Rate:	20	%	S
Plant Uptake:	220	kg/ha/yr	T
Mean daily seepage loss:	3.4	mm	U
Annual N load:	9.46	kg/yr	V
Area for N uptake:	430	m^2	W
Application Rate:	2.5	mm	X

1. Seepage loss (peak) equals deep seepage plus lateral flow:8mm (<10% ksat)

CROP FACTOR

0.7	0.7	0.7	0.6	0.5	0.45	0.4	0.45	0.55	0.65	0.7	0.7	Pasture
0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	0.4	Shade
0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	0.8	Fescue
0.8	0.8	0.7	0.7	0.6	0.6	0.6	0.6	0.7	0.8	0.8	0.8	MAV

NITROGEN UPTAKE:

Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH	Species:	Kg/ha.yr	pH
Ryegrass	200	5.6-8.5	Bent grass	170	5.6-6.9	Grapes	200	6.1-7.9
Eucalyptus	90	5.6-6.9	Couch grass	280	6.1-6.9	Lemons	90	6.1-6.9
Lucerne	220	6.1-7.9	Clover	180	6.1-6.9	C cunn'a	220	6.1-7.9
Tall fescue	150-320	6.1-6.9	Buffalo (soft)	150-320	5.5-7.5	P radiata	150	5.6-6.9
Rye/clover	220		Sorghum	90	5.6-6.9	Poplars	115	5.6-8.5

Appendix D – North East Land Resouce Assessment Data

GEOplan
Geoscience + Planning

Soil landform unit: HGn; Hills on gneiss, Tallangatta / Leneva / Bethanga

Landform pattern	Hills
Elevation (m)	225-450
Annual rainfall (mm)	650-1600
Geomorphic unit	1.3.1 Eastern Uplands; Ridges, Valleys and Hills; High Dissected Ridges and Valley Relief
Geology	Ordovician gneiss and gneissic pegmatite

Locality diagram

Position in landscape



Landform component	1	2	3
Landform element	Steep slopes	Moderate slopes	Gentle footslopes
Slope range (%)	20 - >32	10 - 20	3 - 10
Site drainage	Well to rapidly drained with high permeability	Imperfectly to moderately well drained with low to moderate permeability	Moderately well to well drained with high permeability
Rock outcrop	Nil	0-50%, rock to 0.6 m	0-20%, rock to 2 m
Soil description	Shallow stony loams	Brown loam gradational soils and reddish texture contrast soils	Brown loam gradational soils and reddish texture contrast soils
Present land use	Grazing, public land	Grazing	Grazing
Susceptibility to erosion	Sheet and rill erosion: High	Sheet and rill: Moderate	Sheet and rill: High
	Gully: Moderate	Gully: Moderate	Gully: Moderate
	Landslip: High	Landslip: Moderate	Landslip: Low
	Wind: High	Wind: Moderate	Wind: Moderate
Native vegetation	*Eucalyptus dives, E. macrorhyncha*	*E. dives, E. macrorhyncha, E. goniocalyx*	*E. dives, E. macrorhyncha, E. radiata*

Soil landform map unit: HGn; Hills on Gneiss, Tallangatta / Leneva / Bethanga

Component: 2

Land element: Moderate slopes

GEOplan
Geoscience + Planning

Soils	General description	ASC	PPF
Major	Brown loam gradational soils and reddish texture contrast soils	Brown Kurosol	Dy3.11

Physical characteristics:

Horizon	Depth (cm)	Representative profile description Site ID: Tallangatta 107
A1	0-10	Brown (10YR4/3) fine sandy loam; weak crumb structure; ped sizes 5-10 mm; weak consistence when dry; pH 5.5; abrupt transition to:
B21	10-50	Yellowish brown (10YR5/4) light medium clay; strong angular blocky structure; ped sizes 2-5 mm; firm consistence when moderately moist; reddish brown mottles; pH 4.5; gradual transition to:
B22	50-80+	Yellowish brown (10YR5/4) light medium clay; strong angular blocky structure; ped sizes 30-40 mm; firm consistence when moderately moist; reddish brown mottles; pH 4.5

Chemical characteristics:

Horizon	pH	Salinity (EC)	Internal drainage	Sodicity	Slaking	Dispersion
A1	Strongly acid	Very low	Well	Non sodic	N/A	N/A
B21	Strongly acid	Very low	Imperfect - poorly	Non sodic	N/A	N/A
B22	Strongly acid	Very low	Imperfect - poorly	Non sodic	N/A	N/A

Appendix E – Laboratory Soil Data

Nutrient Advantage®

Nutrient Advantage Advice® — Nutrient Report

GEOPLAN
PO BOX 92
TAWONGA STH
VIC 3698

Report Print Date: 01/08/2017
Agent/Dealer:
Advisor/Contact: NAA Cash Lab User
Phone:
Purchase Order No: GEOPLAN

Grower Name : GEOPLAN
Sample No: 030032973
Paddock Name: BETHANGA B'
Sample Name: B1 HORIZON
Sample Depth (cm): 30 To 50

Nearest Town: TAWONGA
Test Code: E25
Sample Type: Soil
Sampling Date: 18/07/2017

Analyte / Assay	Units	Value
Soil Colour		Brown
Soil Texture		Clay
Emerson Class		2
pH (1:5 Water)		6.7
pH (1:5 CaCl2)		5.5
Elect. Conductivity (EC)	dS/m	0.04
Electrical Conductivity (Sat. Ext.)	dS/m	0.2
Cation Exch. Cap. (CEC)	cmol(+)/kg	11.1
Calcium	cmol(+)/kg	7.5
Magnesium	cmol(+)/kg	3.0
Sodium	cmol(+)/kg	0.10
Potassium	cmol(+)/kg	0.41
Available Potassium	mg/kg	160
Aluminium	cmol(+)/kg	0.1
Aluminium % of Cations	%	1.3
Calcium % of Cations	%	67.0
Magnesium % of Cations	%	27.0
Sodium % of Cations (ESP)	%	0.92
Potassium % of Cations	%	3.70
Calcium/Magnesium Ratio		2.5

Nutrient Advantage®

Nutrient Advantage Advice® — Nutrient Report

GEOPLAN
PO BOX 92
TAWONGA STH
VIC 3698

Report Print Date: 01/08/2017
Agent/Dealer:
Advisor/Contact: NAA Cash Lab User
Phone:
Purchase Order No: GEOPLAN

Grower Name : GEOPLAN
Sample No: 030032973
Paddock Name: BETHANGA B'
Sample Name: B1 HORIZON
Sample Depth (cm): 30 To 50

Nearest Town: TAWONGA
Test Code: E25
Sample Type: Soil
Sampling Date: 18/07/2017

Analyte / Assay	Units	Value
Soil Colour		Brown
Soil Texture		Clay
Emerson Class		2
pH (1:5 Water)		6.7
pH (1:5 CaCl2)		5.5
Elect. Conductivity (EC)	dS/m	0.04
Electrical Conductivity (Sat. Ext.)	dS/m	0.2
Cation Exch. Cap. (CEC)	cmol(+)/kg	11.1
Calcium	cmol(+)/kg	7.5
Magnesium	cmol(+)/kg	3.0
Sodium	cmol(+)/kg	0.10
Potassium	cmol(+)/kg	0.41
Available Potassium	mg/kg	160
Aluminium	cmol(+)/kg	0.1
Aluminium % of Cations	%	1.3
Calcium % of Cations	%	67.0
Magnesium % of Cations	%	27.0
Sodium % of Cations (ESP)	%	0.92
Potassium % of Cations	%	3.70
Calcium/Magnesium Ratio		2.5

ASPAC
Analyses conducted by Nutrient Advantage Laboratory Services
8 South Road, Werribee VIC 3030
NATA Accreditation No: 11958
Tel: 1800 803 453
Certificate of Analysis is available upon request.
Email: lab.feedback@incitecpivot.com.au
Incitec Pivot

GEOplan
Geoscience + Planning